

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: GEYSER SCHOOL DIST 58
103 3RD ST E PO BOX 70
GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-03795

Last Inspected On: 10/15/2014

Operating Permit Renewal Date: 3/26/2018

Contact: (406) 735-4368

Owners/Operators: School Dist 58 Geyser, Owner (406)-735-4368 PO BOX 70
GEYSER MT 59447-0070
Jamie Stahl, UST Class A Operator
Jamie Stahl, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	25	7/19/1990	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
4609			None	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline			Automatic Tank Gauging 0.2	Deferred	
2,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB A 3
US HIGHWAY 87
GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08977
Last Inspected On: 9/19/2014
Operating Permit Renewal Date: 9/25/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
223		9/3/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			ILS-350 , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 1

US HIGHWAY 87

GEYSER, MT 59447

JUDITH BASIN

Sys Fac ID: 23-08986

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/25/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner

(406)-731-6188

39 78TH ST N

MALMSTROM AFB MT 59402-7536

Lana Hedlund, UST Class A Operator

Chris Amann, UST Class B Operator

Ricardo Andrellon, UST Class B Operator

Glen Beck, UST Class B Operator

Allen Brooks, UST Class B Operator

Jonathan Buesch, UST Class B Operator

John Corbett, UST Class B Operator

David Cosner, UST Class B Operator

Ryan Cox, UST Class B Operator

Brian Day, UST Class B Operator

David Degolier, UST Class B Operator

Hudson English, UST Class B Operator

Dustin Hemingway, UST Class B Operator

Aaron Hill, UST Class B Operator

William Hoffmeister, UST Class B Operator

Shane Hofstad, UST Class B Operator

Bethany Kent, UST Class B Operator

James Knudsen, UST Class B Operator

Ryan Kofoed, UST Class B Operator

Jeff Laird, UST Class B Operator

Damon McCarty, UST Class B Operator

Kieth McIlwain, UST Class B Operator

Brian McVay, UST Class B Operator

Ronald Miller, UST Class B Operator

Michael Murieen, UST Class B Operator

Jeff Nelson, UST Class B Operator

Shawn O'Grady, UST Class B Operator

Chris Ploof, UST Class B Operator

Issac Price, UST Class B Operator

Brian Rayner, UST Class B Operator

Adam Reathaford, UST Class B Operator

Cameron Smith, UST Class B Operator

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 1
US HIGHWAY 87
GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08986
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/25/2017

Contact: Jim Hodges,
Jimmy Sonefelt, UST Class B Operator
Michael Stokes, UST Class B Operator
Kyle Topp, UST Class B Operator
Jason Vike, UST Class B Operator
James Wooderchak, UST Class B Operator
Paul Ziemba, UST Class B Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	53	5/2/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
224		9/5/2014	Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Impressed Current
Diesel		7/1/2014	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 7
US HIGHWAY 87
GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08992
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
227		10/8/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 8
 US HIGHWAY 87
 GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08993

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/26/2017

Contact: William McLaughlin, (406) 731-6188

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
 MALMSTROM AFB MT 59402-7536
 Lana Hedlund, UST Class A Operator
 Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	02	1/1/2014	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
5466		9/5/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root	Not Listed	Yes

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 9
 US HIGHWAY 87
 GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08994
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
 MALMSTROM AFB MT 59402-7536
 Lana Hedlund, UST Class A Operator
 Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
229		10/15/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 10
US HIGHWAY 87
GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08995

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
230		10/29/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of GEYSER

Location: MALMSTROM AFB B 11
US HIGHWAY 87
GEYSER, MT 59447 JUDITH BASIN

Sys Fac ID: 23-08996

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	26	6/21/1989	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
231		10/22/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of HOBSON

Location: HOBSON SCHOOL DIST 25
CENTRAL AVE
HOBSON, MT 59452 JUDITH BASIN

Sys Fac ID: 23-05904

Last Inspected On: 5/26/2015

Operating Permit Renewal Date: 8/22/2018

Contact: Cody McDonald, (406) 423-5483

Owners/Operators: School Dist 25 Hobson, Owner

(406)-423-5483

PO BOX 410
HOBSON MT 59452-0410

Michael Woods, UST Class A Operator

Michael Woods, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	25	8/18/1990	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff)
1388		6/26/2015	None	Secondary Containment Chase	Yes
Currently in Use			Auto Dialer	U.S. Suction	Galvanic
Heating Oil		5/26/2015	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
10,000			TLS-300 , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of HOBSON

Location: WOODHALL DISTRIBUTING
21 SAWMILL RD
HOBSON, MT 59452 JUDITH BASIN
Contact: Wyatt Woodhall, (406) 366-0308

Sys Fac ID: 23-06450
Last Inspected On: 3/24/2014
Operating Permit Renewal Date: 7/10/2017

Owners/Operators: Woodhall Distributing - Stanford, Owner (406)-566-2671 PO BOX 9
STANFORD MT 59479-0009
Greg Econom, UST Class A Operator
Wyatt Woodhall, UST Class A Operator
Greg Econom, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	17	4/1/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4745			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		3/24/2014	Automatic Tank Gauging 0.2	Deferred	
6,000			Gilbarco EMC Basic , Gilbarco		
6	17	4/1/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4746			None	None	Yes
Currently in Use			Not Required	Safe Suction	Galvanic
Gasoline		3/24/2014	Automatic Tank Gauging 0.2	Deferred	
6,000			Gilbarco EMC Basic , Gilbarco		

Facility Summary in JUDITH BASIN County in the City of HOBSON

Location: MALMSTROM AFB L 9
ROAD 400
HOBSON, MT 59452 JUDITH BASIN

Sys Fac ID: 23-09104
Last Inspected On: 7/24/2013
Operating Permit Renewal Date: 7/31/2016

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536

Lana Hedlund, UST Class A Operator
James Hodges, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	22	5/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
243		8/14/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of HOBSON

Location: MALMSTROM AFB M 8
ROAD 400
HOBSON, MT 59452 JUDITH BASIN

Sys Fac ID: 23-09114
Last Inspected On: 7/12/2013
Operating Permit Renewal Date: 7/24/2016

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
James Hodges, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	5/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
244		9/26/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000					

Facility Summary in JUDITH BASIN County in the City of MOCCASIN

Location: MALMSTROM AFB C 4
US HIGHWAY 87
MOCCASIN, MT 59462 JUDITH BASIN

Contact: Jim Hodges,

Sys Fac ID: 23-09000
Last Inspected On: 3/31/2014
Operating Permit Renewal Date: 7/8/2017

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536

Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
235		6/18/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of MOCCASIN

Location: MALMSTROM AFB C 5
US HIGHWAY 87
MOCCASIN, MT 59462 JUDITH BASIN

Sys Fac ID: 23-09001
Last Inspected On: 4/1/2014
Operating Permit Renewal Date: 7/22/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
James Hodges, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
236		7/2/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of MOCCASIN

Location: MALMSTROM AFB C 6
ROAD 239
MOCCASIN, MT 59462 JUDITH BASIN

Sys Fac ID: 23-09002
Last Inspected On: 4/2/2014
Operating Permit Renewal Date: 7/8/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
237		7/16/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of MOCCASIN

Location: MALMSTROM AFB C 7
ROAD 239
MOCCASIN, MT 59462 JUDITH BASIN

Sys Fac ID: 23-09003
Last Inspected On: 4/2/2014
Operating Permit Renewal Date: 7/8/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
238		7/9/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of MOCCASIN

Location: MALMSTROM AFB M 9
US HIGHWAY 87
MOCCASIN, MT 59462 JUDITH BASIN

Sys Fac ID: 23-09115
Last Inspected On: 7/12/2013
Operating Permit Renewal Date: 7/24/2016

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	5/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
245		10/3/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of MOCCASIN

Location: MALMSTROM AFB M 10
 US HIGHWAY 87
 MOCCASIN, MT 59462 JUDITH BASIN

Contact: Jim Hodges,

Sys Fac ID: 23-09116
Last Inspected On: 8/2/2013
Operating Permit Renewal Date: 8/6/2016

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
 MALMSTROM AFB MT 59402-7536

Lana Hedlund, UST Class A Operator
 James Hodges, UST Class A Operator
 Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	22	5/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
246		10/10/2013	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of RAYNESFORD

Location: MALMSTROM AFB A 4
ROAD 427
RAYNESFORD, MT 59469 JUDITH BASIN

Sys Fac ID: 20-08978
Last Inspected On: 9/19/2014
Operating Permit Renewal Date: 9/25/2017

Contact: Jim Hodges, (406) 731-6163

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	6/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
221		9/3/2014	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			ILS-350 , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of RAYNESFORD

Location: KIBBEY KORNER TRUCK STOP
US HIGHWAY 87 & ROUTE 427 PO BOX 197
RAYNESFORD, MT 59469 JUDITH BASIN

Sys Fac ID: 23-03301
Last Inspected On: 7/11/2013
Operating Permit Renewal Date: 8/4/2016

Contact: (406) 738-4400

Owners/Operators: Mountain View Coop, Owner (406)-453-2435 ATTN DAVE DOUGLAS
2200 OLD HAVRE HWY
BLACK EAGLE MT 59414-1043

David Douglas, UST Class A Operator
David Douglas, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	19	9/1/1996	Bare Steel	Fiberglass Reinforced Plastic	
1030	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	MLLD Line Tightness Testing	
10,000		5/21/2010			
5	19	9/1/1996	Bare Steel	Fiberglass Reinforced Plastic	
1029	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	MLLD Line Tightness Testing	
10,000		5/21/2010			
6	19	9/1/1996	Bare Steel	Fiberglass Reinforced Plastic	
1028	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	MLLD Line Tightness Testing	
8,000		5/21/2010			
7	19	9/1/1996	Bare Steel	Fiberglass Reinforced Plastic	
1027	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	MLLD Line Tightness Testing	
8,000		5/21/2010			

Facility Summary in JUDITH BASIN County in the City of RAYNESFORD

Location: KIBBEY KORNER TRUCK STOP
US HIGHWAY 87 & ROUTE 427 PO BOX 197
RAYNESFORD, MT 59469 JUDITH BASIN

Sys Fac ID: 23-03301

Last Inspected On: 7/11/2013

Operating Permit Renewal Date: 8/4/2016

Contact: (406) 738-4400

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	19	9/1/1996	Bare Steel	Fiberglass Reinforced Plastic	, Not Applicable
1026	Yes		None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	MLLD Line Tightness Testing	
25,000		5/21/2010			

Facility Summary in JUDITH BASIN County in the City of RAYNESFORD

Location: MALMSTROM AFB A 1
US HIGHWAY 87
RAYNESFORD, MT 59469 JUDITH BASIN

Sys Fac ID: 23-08974

Last Inspected On: 9/19/2014

Operating Permit Renewal Date: 9/19/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536

Lana Hedlund, UST Class A Operator
James Hodges, UST Class A Operator
Chris Amann, UST Class B Operator
Ricardo Andrillon, UST Class B Operator
Glen Beck, UST Class B Operator
Allen Brooks, UST Class B Operator
Jonathan Buesch, UST Class B Operator
John Corbett, UST Class B Operator
David Cosner, UST Class B Operator
Ryan Cox, UST Class B Operator
Brian Day, UST Class B Operator
David Degolier, UST Class B Operator
Hudson English, UST Class B Operator
Dustin Hemingway, UST Class B Operator
Aaron Hill, UST Class B Operator
William Hoffmeister, UST Class B Operator
Shane Hofstad, UST Class B Operator
Bethany Kent, UST Class B Operator
James Knudsen, UST Class B Operator
Ryan Kofoed, UST Class B Operator
Jeff Laird, UST Class B Operator
Damon McCarty, UST Class B Operator
Kieth McIlwain, UST Class B Operator
Brian McVay, UST Class B Operator
Ronald Miller, UST Class B Operator
Michael Murieen, UST Class B Operator
Jeff Nelson, UST Class B Operator
Shawn O'Grady, UST Class B Operator
Chris Ploof, UST Class B Operator
Issac Price, UST Class B Operator
Brian Rayner, UST Class B Operator
Adam Reathaford, UST Class B Operator

Facility Summary in JUDITH BASIN County in the City of RAYNESFORD

Location: MALMSTROM AFB A 1
US HIGHWAY 87
RAYNESFORD, MT 59469 JUDITH BASIN

Sys Fac ID: 23-08974
Last Inspected On: 9/19/2014
Operating Permit Renewal Date: 9/19/2017

Contact: Jim Hodges,
Cameron Smith, UST Class B Operator
Jimmy Sonefelt, UST Class B Operator
Michael Stokes, UST Class B Operator
Kyle Topp, UST Class B Operator
Jason Vike, UST Class B Operator
James Wooderchak, UST Class B Operator
Paul Ziemba, UST Class B Operator
Lana Hedlund, UST Class B Global Operator
James Hodges, UST Class B Global Operator
Mark W Johnson, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	53	5/2/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
222		9/3/2014	Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Impressed Current
Diesel		7/1/2014	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB B 3
MT HIGHWAY 81
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 14-08988

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges, (406) 731-6167

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	8/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
163		9/3/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB B 4
MT HIGHWAY 80
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 14-08989

Last Inspected On: 12/5/2014

Operating Permit Renewal Date: 9/15/2017

Contact: Jim Hodges, (406) 731-6167

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
164		9/24/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: BY WAY SERVICE STATION
MT HIGHWAY 80 & US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-01526

Last Inspected On: 9/2/2014

Operating Permit Renewal Date: 10/23/2017

Contact: Shirley Froberg, (406) 566-2203

Owners/Operators: Shirley Woodhall, Owner (406)-566-2203 PO BOX 485
STANFORD MT 59479-0485

Shirley Woodhall, UST Class A Operator
Wyatt Woodhall, UST Class A Operator
Gloria Hungate, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	19	9/1/1996	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
4410			None	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel		9/2/2014	Automatic Tank Gauging 0.2	Deferred	
5,000		9/1/2011	TLS-350/Gilbarco EMC , Veeder Root		
7	17	10/1/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4411			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		9/2/2014	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
10,000		9/2/2014	TLS-350/Gilbarco EMC , Veeder Root		
8	17	10/1/1998	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
4412			None	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Gasoline		9/2/2014	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
5,000		9/2/2014	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: STANFORD SCHOOL DIST 12
104 4TH AVE S
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-01938

Last Inspected On: 8/21/2013

Operating Permit Renewal Date: 10/11/2016

Contact: Arnie Smith, (406) 566-2265

Owners/Operators: School Dist 12 Stanford, Owner (406)-566-2265 PO BOX 506
STANFORD MT 59479-0506
Arnie Smith, UST Class A Operator
Arnie Smith, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
3	17	10/9/1998	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1893			Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	U.S. Suction	Not Applicable
Heating Oil			Manual Interstitial Monitor	MLLD Line Tightness Testing	
8,000		8/21/2013			

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: WOODHALL DISTRIBUTING
MT HIGHWAY 80 & MAIN ST
STANFORD, MT 59479 JUDITH BASIN

Contact: Wyatt Woodhall, (406) 566-2671

Sys Fac ID: 23-03303
Last Inspected On: 5/13/2013
Operating Permit Renewal Date: 8/4/2016

Owners/Operators: Woodhall Distributing - Denton, Owner (406)-567-2266 PO BOX 1018
DENTON MT 59430-1018

Wyatt Woodhall, UST Class A Operator
Greg Econom, UST Class B Operator
Gloria Hungate, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	17	7/6/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1031			None	None	Yes
Currently in Use		7/6/2008	Not Required	Safe Suction	Not Applicable
Gasoline			Vapor Monitoring	Deferred	
2,000					
5	17	7/6/1998	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
1032			None	None	Yes
Currently in Use		7/6/2008	Not Required	Safe Suction	Not Applicable
Gasoline			Vapor Monitoring	Deferred	
2,000					

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB B 2
MT HIGHWAY 80
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-08987
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
225		9/17/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB B 6
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-08991
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
226		10/1/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 1
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-08997

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges, (406) 731-3247

Owners/Operators: 341 CES CEANQ, Owner

(406)-731-6188

39 78TH ST N
MALMSTROM AFB MT 59402-7536

Lana Hedlund, UST Class A Operator
Chris Amann, UST Class B Operator
Ricardo Andrillon, UST Class B Operator
Glen Beck, UST Class B Operator
Allen Brooks, UST Class B Operator
Jonathan Buesch, UST Class B Operator
John Corbett, UST Class B Operator
David Cosner, UST Class B Operator
Ryan Cox, UST Class B Operator
Brian Day, UST Class B Operator
David Degolier, UST Class B Operator
Hudson English, UST Class B Operator
Dustin Hemingway, UST Class B Operator
Aaron Hill, UST Class B Operator
William Hoffmeister, UST Class B Operator
Shane Hofstad, UST Class B Operator
Bethany Kent, UST Class B Operator
James Knudsen, UST Class B Operator
Ryan Kofoed, UST Class B Operator
Jeff Laird, UST Class B Operator
Damon McCarty, UST Class B Operator
Kieth McIlwain, UST Class B Operator
Brian McVay, UST Class B Operator
Ronald Miller, UST Class B Operator
Michael Murieen, UST Class B Operator
Jeff Nelson, UST Class B Operator
Shawn O'Grady, UST Class B Operator
Chris Ploof, UST Class B Operator
Issac Price, UST Class B Operator
Brian Rayner, UST Class B Operator
Adam Reathaford, UST Class B Operator
Cameron Smith, UST Class B Operator

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 1
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-08997
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges, (406) 731-3247

Jimmy Sonefelt, UST Class B Operator
Michael Stokes, UST Class B Operator
Kyle Topp, UST Class B Operator
Jason Vike, UST Class B Operator
James Wooderchak, UST Class B Operator
Paul Ziemba, UST Class B Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	53	5/2/1962	Cathodically Protected Steel	Flexible Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
232		9/10/2014	Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Not Required	U.S. Suction	Impressed Current
Diesel		7/1/2014	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
12,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 2
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-08998
Last Inspected On: 3/31/2014
Operating Permit Renewal Date: 7/8/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
233		6/11/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 3
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-08999
Last Inspected On: 3/31/2014
Operating Permit Renewal Date: 7/8/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/11/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
234		8/21/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 8
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-09004
Last Inspected On: 9/24/2014
Operating Permit Renewal Date: 10/7/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
239		7/30/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Safe Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 9
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-09005
Last Inspected On: 9/24/2014
Operating Permit Renewal Date: 10/7/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
240		8/6/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 10
US HIGHWAY 87
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-09006
Last Inspected On: 9/24/2014
Operating Permit Renewal Date: 10/7/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
241		12/2/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB C 11
 US HIGHWAY 87
 STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 23-09007
Last Inspected On: 9/22/2014
Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges,

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
 MALMSTROM AFB MT 59402-7536
 Lana Hedlund, UST Class A Operator
 James Hodges, UST Class A Operator
 Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	10/1/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
242		6/25/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in JUDITH BASIN County in the City of STANFORD

Location: MALMSTROM AFB B 5
MT HIGHWAY 80
STANFORD, MT 59479 JUDITH BASIN

Sys Fac ID: 26-08990

Last Inspected On: 9/22/2014

Operating Permit Renewal Date: 9/26/2017

Contact: Jim Hodges, (406) 731-6167

Owners/Operators: 341 CES CEANQ, Owner (406)-731-6188 39 78TH ST N
MALMSTROM AFB MT 59402-7536
Lana Hedlund, UST Class A Operator
Lana Hedlund, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
2	23	9/10/1992	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff), High Level Alarm
258		9/24/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Auto Dialer	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,000			TLS-350/Gilbarco EMC , Veeder Root		